



THRUST PLATE 6269
 NOTE: THOROUGHLY COAT THRUST PLATE WITH MOTOR OIL PRIOR TO INSTALLATION OF THRUST PLATE

SCREW 2 REQ'D TIGHTEN TO 8-14 N·m (70-124 LB-IN)

THOROUGHLY COAT CAM BEARINGS IN BLOCK WITH MOTOR OIL PRIOR TO INSTALLATION

