

**INSTALL NEW
DRIVESHAFT
BEARING
RETAINER
CIRCLIP 3Z498
DO NOT OVER
EXPAND OR
TWIST**

**RETAINING
CLIP GROOVE**

**INBOARD CV JOINT
HOUSING**

